

This diagram shows how to convert a 4-20 mA signal to 0-5 V for input into an ALC modules

